

LOCTITE®

“Do it Right” User’s Guide

The “When, Where & How” to use
LOCTITE® Maintenance Products



Henkel

TABLE OF CONTENTS


LOCTITE® MAINTENANCE PRODUCTS

The primary function of this User's Guide is to help you, the maintenance professional, with the proper use of LOCTITE® products. A wide variety of preventative maintenance, as well as repair techniques, are explained in step-by-step detail. Consider this a supplemental service manual for every piece of equipment in your plant. Our goal is to make it easier for you to use our products, to your benefit, for faster repair times, reduced downtime, and extended equipment life. Additional information on these products, as well as others, is available by contacting your local Henkel adhesives and sealants representative at the telephone number listed on the back cover of this guide.

CONTENT		PAGE
■	INTRODUCTION	4
■	THREADLOCKING	5
	Through Holes (Bolts and Nuts)	5
	Blind Holes (Cap Screws, Etc.)	5
	Blind Holes (Studs, Etc.)	6
	Adjustment Screws	6
	Pre-assembled Fasteners	7
	High Strength Disassembly	7
	Product Selector	8
	Heat Seizure Prevention - Anti-seize	8
■	THREAD SEALING	9
	Standard Fittings - Pipes, Hydraulic, or Air	9
	Pipe Unions	9
	Compression Fittings	10
	Flared / Swaged Fittings	10
	Hose Ends - Air & Hydraulics	11
	Thread Sealing Quick Selector	11
■	PUNCTURE SEALING	12
	Tanks, Vessels, etc.	12
■	POROSITY SEALING	13
	Existing Welds	13
	New Welds	13

TABLE OF CONTENTS

CONTENT		PAGE
■ FORM-IN-PLACE GASKETING	Sealing Cast Rigid Flanges	14
	Gasketing Quick Selector	14
■ GASEKT DRESSING	Sealed Flanges	15
■ FORM-IN-PLACE SILICONES	Stamped or Sheet Metal Flanges	16
	Silicone Quick Selector	17
■ STRENGTHEN KEYED ASSEMBLIES	Standard Duty	18
	Heavy Duty	19
	Repairing Badly Wallowed Keyway	20
■ SHAFT MOUNTED ASSEMBLIES	Repairing Badly Worn Shaft	21
	Slip Fit - Light Duty	22
	Slip Fit - Heavy Duty	23
	Press Fit	24
	Shrink Fit	25
■ HOUSED COMPONENTS	Slip Fit - Light Duty	26
	Slip Fit - Heavy Duty	27
	Repairing Badly Worn Housing	28
	Component Centering	29
	Sealing/Retaining - Metallic Seal	30
■ RETAINING COMPOUNDS	Quick Selector	31
■ BONDING	Proper Joint Design	32
	O-ring Marking	33
	Bonding Metal Label	33
	Filling Cracks	34
	Structural Bonding	34
	Adhesive Quick Selector	35
	Guide to Successful Bonding	36
■ CLEANING	General Purpose Parts Cleaning	37
■ RUST ROOFING	General Info	38
■ TROUBLESHOOTING	Checklist	39
	Limitation Of Warranty	39
	Fluid Compatibility Chart	40-43
■ MANUFACTURING RELIABILITY WORKSHOP		44



INTRODUCTION

INTRODUCTION TO ANAEROBIC ADHESIVES AND SEALANTS

Anaerobic adhesives and sealants were developed by the founder of LOCTITE® Corporation, now Henkel Corporation, in 1953 and, since then, they have significantly evolved to meet the highest requirements of equipment manufacturers, maintenance and overhaul.

Anaerobic adhesives and sealants are resins that convert from liquid to a tough structural solid in the absence of air and the presence of metal. The primary functions of anaerobic resins are:

Threadlocking	Thread Sealing	Gasketing	Retaining

Each one of these functions is based upon control of five major variables: strength, viscosity, adhesion, flexibility, and temperature resistance. These five parameters give anaerobics users considerable latitude in adjusting properties for optimum performance in specific application areas.

Another variable that should be considered is the substrate in which the adhesive will be applied. For certain substrates or other special requirements, the use of primer is recommended.

WHY USE A PRIMER?

1. Primers activate inactive surfaces.
2. Primers speed cure times for faster return to service.
3. Primers speed curing through larger gaps and deep threads.
4. Primers substantially speed cure times on cold parts.
5. Primers act as cleaning agents.


Active surfaces (Primer optional): Brass, copper, bronze, iron, soft steel, nickel.

Inactive surfaces (Primer required): Aluminum, stainless steel, magnesium, zinc, black oxide, cadmium, titanium, others.




THREADLOCKING

THROUGH HOLES (BOLTS AND NUTS)



1. Clean all threads (bolt and nut) with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser, if required.
2. If necessary, spray all threads with LOCTITE® SF 7649™ Primer N™. Allow to dry.
3. Select the proper strength LOCTITE® Threadlocker product.
4. Insert bolt into thru hole assembly.
5. Apply several drops of liquid Threadlocker onto bolt at targeted tightened nut engagement area.
6. Assemble and tighten nut as usual.

BLIND HOLES (CAP SCREWS, ETC.)





1. Clean all threads (bolt and hole) with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser, if required.
2. If necessary, spray (bolt and hole) with LOCTITE® SF 7649™ Primer N™. Allow 30 seconds to dry.
3. Select the proper strength Threadlocking product.
4. Squirt several drops down the sides of the female threads.
5. Apply several drops to bolt.
6. Tighten as usual.

Note: Using LOCTITE® Threadlockers will virtually eliminate stripped threads in aluminum or Magnesium housings caused by galvanic corrosion.




THREADLOCKING

BLIND HOLES (STUDS, ETC.)



1. Clean all threads (bolt and hole) with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser, if required.
2. If necessary, spray all threads with LOCTITE® SF 7649™ Primer N™. Allow to dry.
3. Squirt several drops of LOCTITE® 263™ Threadlocker down the sides of the female threads.
Note: Use LOCTITE® 277™ Threadlocker if stud is over 1" diameter.
4. Apply several drops of LOCTITE® 263™ Threadlocker onto stud threads.
5. Install studs.
6. Position cover, head, etc.
7. Apply drops of LOCTITE® 243™ Threadlocker onto exposed threads.
8. Tighten nuts as required.

BLIND HOLES (STUDS, ETC.)




1. Adjust screw to proper setting.
2. Apply several drops of LOCTITE® 290™ Threadlocker at screw and body juncture.
3. Avoid touching bottle tip to metal.
Note: If re-adjustment is difficult, apply heat to screw with soldering gun (230°C). LOCTITE® 220™ Threadlocker is a weaker version of LOCTITE® 290™ Threadlocker.



THREADLOCKING


PRE-ASSEMBLED FASTENERS



1. Clean bolts and nuts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser, if required.
2. Assemble components.
3. Tighten nuts.
4. Apply several drops of LOCTITE® 290™ Threadlocker at the nut and bolt juncture.
5. Avoid touching bottle tip to metal.

Note: For preventive maintenance on existing equipment: RE-TIGHTEN nuts and apply LOCTITE® 290™ Threadlocker at the nut and bolt juncture.

HIGH STRENGTH DISASSEMBLY



1. Apply localized heat to nut or stud (232°C for 5 minutes).
2. Disassemble while HOT.

Note: Use standard hand tools for disassembly of low and medium strength Threadlockers.



THREADLOCKING

PRODUCT SELECTOR

LOCTITE® THREADLOCKER QUICK SELECTOR

Use	Strength	Product	Color
Small Screws	Low	222™	Purple
Pre-Assembled	Low	220™	Blue
Nuts & Bolts	Medium	243™ (Up)	Blue
Pre-Assembled	Medium	290™	Green
Nuts & Bolts	High	263™ (Up)	Red
Studs (up to 1")	High	263™ (Up)	Red
Studs (over 1")	High	277™	Red

HEAT SEIZURE PREVENTION - ANTI-SEIZE

Anti-Seize compounds protect mated metal parts against friction, galling, and corrosion. Anti-Seize also reduces wrench torque to facilitate assembly and disassembly of threaded connections.


LOCTITE® ANTI-SEIZE QUICK SELECTOR

Product	Max Temp.	IDH No.	Pack Size
LOCTITE® LB 8008 C5-A Copper Anti-Seize Lubricant	982°C	2096331	1 kg
LOCTITE® LB 8150 Silver Grade Anti-Seize	870°C	833783	500 g
LOCTITE® LB 771 Nickel Anti-Seize	1315°C	1751839	1 lb.
LOCTITE® LB 8009 Heavy Duty Anti-Seize	1315°C	1751851	510 g



THREAD SEALING

STANDARD FITTINGS - PIPE, HYDRAULIC, OR AIR




1. Clean parts of contamination. If necessary, spray LOCTITE® SF 7649™ Primer N™ onto threaded parts (male and female). Allow to dry.
Note: Primer is not required for brass parts.
2. Apply a band of LOCTITE® PST® Pipe Sealant to male threads starting one to two threads from end of pipe.
3. Assemble parts snugly. Do not overtighten.
4. If initial pressure exceeds 6.89 N/mm²*, wait 30 minutes before pressurizing.

Note:

- For fine threads of hydraulic & pneumatic connectors use LOCTITE® 542™ Thread Sealant.
- For course threads, medium strength use LOCTITE® 577™ Thread Sealant.
- For stainless steel components, use LOCTITE® 567™ PST® Pipe Sealant.
- For general purpose thread sealing, use LOCTITE® 565™ PST® Pipe Sealant.
- For fine filtration systems requiring zero contamination, use LOCTITE® 545™ Hydraulic/Pneumatic Sealant.
- If sealing chemicals or strong acids/bases, refer to Fluid Compatibility Chart.
- Do not use on oxygen or strong oxidizers (chlorine).

*Depending on conditions

PIPE UNIONS




1. Disassemble and, if necessary, spray all components with LOCTITE® SF 7649™ Primer N™. Allow to dry.
2. Apply a thin coating of LOCTITE® PST® Pipe Sealant to union face.
3. Apply a band of LOCTITE® PST® Pipe Sealant to male threads.
4. Assemble parts snugly.




THREAD SEALING

COMPRESSION FITTINGS



1. Slide fitting nut and ferrule back approximately $\frac{3}{4}$ " from end of tubing.
2. If necessary, spray the entire assembly with LOCTITE® SF 7649™ Primer N™. Allow to dry.
Note: Primer is not required for brass parts.
3. Apply a thin coating of LOCTITE® PST® Pipe Sealant to tubing where ferrule will be located.
5. Slide ferrule forward over LOCTITE® PST® Pipe Sealant coated tubing, then apply a thin bead of LOCTITE® PST® Pipe Sealant coating to ferrule.
6. Slide ferrule forward over LOCTITE® PST® coated tubing.
7. Apply a small band of LOCTITE® PST® Pipe Sealant to male threads.
8. Assemble and tighten normally.
Note: Do not use on plastic fittings or tubing.

FLARED/SWAGED FITTINGS




1. Disassemble and if necessary, spray all components with LOCTITE® SF 7649™ Primer N™. Allow to dry.
2. Apply a thin coating of LOCTITE® PST® Pipe Sealant to fitting face.
3. Apply a band of LOCTITE® PST® Pipe Sealant to male threads.
4. Assemble parts snugly.



THREAD SEALING

HOSE ENDS - AIR & HYDRAULIC



1. If necessary, spray adapter threads with LOCTITE® SF 7649™ Primer N™. Allow to dry.
2. Insert barbed hose stem into hose I.D. with slight twisting motion.
3. Install appropriate hose clamp.
4. Apply a band of LOCTITE® PST® Pipe Sealant to male hose stem threads upon installation or adding accessory device. Tighten snugly.

Note: LOCTITE® PST® Pipe Sealant may attack synthetic rubber tubing.

LOCTITE® THREAD SEALING QUICK SELECTOR (TAPERED THREADS)

Application	Product	Primer	Max Pressure	Temp Range
Fine Threads	542™	N™	68.9 N/mm ²	-54° to +150°C
General Purpose	Thread Sealant			
Coarse Threads	572™	N™	68.9 N/mm ²	-54°C to +150°C
General Purpose	Thread Sealant			
Coarse Threads	577™ (Up)	N™/T™	68.9 N/mm ²	-54°C to +180°C
Medium Strength	Thread Sealant			
Stainless Steel and All Other Metal Fittings	567™ (Up) PST® Pipe Sealant	N™	68.9 N/mm ²	-54°C to +250°C
Most Metal Fittings Except Stainless Steel	565™ PST® Pipe Sealant	N™	68.9 N/mm ²	-54°C to +150°C
High Filtration/Zero Contamination Systems	545™ Hydraulic/ Pneumatic Sealant	T™	68.9 N/mm ²	-54°C to +150°C

DO NOT USE THESE PRODUCTS ON OXYGEN OR STRONG OXIDIZERS.


FLUID COMPATIBILITY QUESTIONS?

1. Refer to Fluid Compatibility Chart.
2. Contact your local Industrial Distributor.
3. Call Henkel Technical Services.



PUNCTURE SEALING

TANKS, VESSELS, ETC.



1. **IMPORTANT! TAKE PROPER SAFETY PRECAUTIONS IF WORKING WITH FLAMMABLE LIQUID TANKS. AVOID USE WITH COMPRESSIBLE GASSES.**
2. Clean the repair area with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
3. Roughen a 1"- 2" radius around hole with emery cloth. Clean again.
4. Prepare a metal disc patch slightly larger than hole.
5. Mix LOCTITE® PC 3473 Fast Steel Putty (A and B) per directions.
6. Apply a thin layer of LOCTITE® PC 3473 Fast Steel Putty to roughened area.
7. Immediately position disc patch over hole.
8. Apply a cover layer of LOCTITE® PC 3473 Fast Steel Putty over disc patch and Epoxy layer 1.
9. Allow to cure before service use:
 - a. Liquid storage - 1 hour
 - b. Low pressure (under 1.03 N/mm²) - 1 hour
 - c. High Pressure - Not Recommended over 1.03 N/mm²
10. Paint as required.

SEALING CRACKS

1. Drill termination holes to prevent further cracking.
2. Follow directions above. Modify as needed.


SEALING PIN-HOLES

1. Follow directions above. No disc patch needed.



POROSITY SEALING

EXISTING WELD POROSITIES AND CASTINGS



1. **IMPORTANT! TAKE PROPER SAFETY PRECAUTIONS IF WORKING WITH FLAMMABLE LIQUID TANKS. AVOID USE WITH COMPRESSIBLE GASSES.**
2. Wire brush to remove paint, rust, etc. from repair area.
3. Clean repair area with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
4. Apply localized heat to bring repair area to approx. 120°C.
5. Allow repair area to cool to approx. 80°C.
6. Brush or spray sealant on repair area.

Note:

- Steel - Use LOCTITE® 290™ Threadlocker at 80°C.
- Aluminum/Stainless Steel - Use LOCTITE® 290™ Threadlocker at 50°C.

Note:

- Not recommended for “blowholes”
 - Maximum porosity sealed - 0.005”
7. Allow to cure for 30 minutes (High Pressure above 1.03 N/mm² - 1 hour)
 8. Clean with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser to remove excess sealant. Do not grind.
 9. Paint as required.

Note: Casting repair uses same procedure.


SEALING NEW WELDS - PREVENTATIVE MAINTENANCE

1. Remove all slag and scale while hot.
2. Apply sealant when weld is 80°C and falling.
3. Follow information above.



FORM-IN-PLACE GASKETING

SEALING CAST RIGID FLANGES



1. Remove old gasketing material and other heavy contaminants with LOCTITE® SF 790 Chisel® Gasket Remover. Use mechanical removal technique if required.
Note: Avoid grinding.
2. Clean both flanges with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser, if required.
3. Spray LOCTITE® SF 7649™ Primer N™ on only one surface. Allow 1-2 minutes to dry.
4. Apply a continuous bead of LOCTITE® Flange Sealant to the other surface.
Note: Circle all bolt holes with sealant, if appropriate.
5. Mate Parts. Assemble and tighten as required.
Note: Immediate assembly not required; however avoid delays over 45 minutes.
6. Allow to cure:
 - a. No pressure - immediate service
 - b. Low pressure (up to 3.44 N/mm²) - 30 to 45 minutes
 - c. High pressure (3.44 N/mm² to 17.23 N/mm²) - 4 hours
 - d. Extreme high pressure (17.23 N/mm² to 34.47 N/mm²) - 24 hours


LOCTITE® GASKETING QUICK SELECTOR

Use	Product	Gap Fill	Temp Range
Rigid and semi rigid metal flanges	574™	0.010"	-54°C to 150°C
Rigid iron, steel and aluminium flanges	518™ (Up)	0.010"	-54°C to 150°C
Flexible applications	515™	0.010"	-54°C to 150°C
Hi-Temp	510™	0.010"	-54°C to 204°C



GASKET DRESSING

SEALED FLANGES




1. Remove old gasketing material and other heavy contaminants with LOCTITE® SF 790 Chisel® Gasket Remover. Use mechanical removal technique if required.
Note: Avoid grinding.
2. Clean both flanges with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
3. Spray LOCTITE® SF 7649™ Primer N™ on both flange faces and both sides of the precut gasket. Allow 1-2 minutes to dry.
4. Smear LOCTITE® Flange Sealant to both sides of precut gasket with a clean applicator.
5. Place coated gasket on flange surface and assemble parts immediately.
Note:
 - If cover bolts into blind holes (as above), apply LOCTITE® 243™ Threadlocker into hole and on threads. Tighten normally.
 - If through bolt assembly, apply LOCTITE® 243™ Threadlocker to bolt threads.
6. Tighten normally.




FORM-IN-PLACE SILICONES

STAMPED OR SHEET METAL FLANGES



1. Remove old gasketing material and other heavy contaminants with LOCTITE® SF 790 Chisel® Gasket Remover.
2. Clean both flanges with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
3. Apply a continuous bead of High Performance Silicones to sealing surface. Circle all bolt holes.
Note:
 - Use proper bead diameter to seal flange width and depth 3mm or sufficed to cover flange.
 - Minimize excessive material “squeeze in”.
4. Assemble within 10 minutes by pressing together. Tighten as required.
5. Clean up any excess or squeeze out.
6. Cure times will vary with temperature, humidity, and gap. Typical full cure time is 24 hours.

DISASSEMBLY



- Disassemble flange using hand tools.
Note: For anaerobic/silicone gaskets, clean with LOCTITE® SF 790 Chisel® Gasket remover.

REASONS TO USE LOCTITE® ANAEROBIC GASKETING COMPOUNDS INSTEAD OF STANDARD RTV SILICONES

- LOCTITE® ANAEROBIC GASKETING COMPOUNDS ARE RESISTANT TO GASOLINE AND FUEL OILS. Silicones should not be used to seal fuel systems. They swell and lose sealing ability.
- LOCTITE® ANAEROBIC GASKETING COMPOUNDS RESIST “BLOW-OUT”. Silicones are not recommended for high pressure applications.



FORM-IN-PLACE SILICONES

HIGH PERFORMANCE SILICONES

LOCTITE® HIGH PERFORMANCE RTV SILICONES QUICK SELECTOR

Product	Use	Gap Fill	Temp Range
587™ Blue	General	0.250"	-59°C to 250°C
5699™ Grey	General	0.125"	-59°C to 329°C
5910™ Black	High Adhesion	0.240"	-54°C to 260°C
5920™ Copper	Hi-Temp	0.250"	-54°C to 371°C

1. Continuous service. Intermittent temperature higher than established range.

Note: Silicones used at extreme high temperatures can seal but lose various properties.


REASONS TO USE LOCTITE® HIGH PERFORMANCE RTV SILICONES INSTEAD OF STANDARD RTV SILICONES

- LOCTITE® HIGH PERFORMANCE SILICONES WILL NOT CORRODE STEEL OR ALUMINUM. Standard RTV acetoxy silicones (vinegar smell) should not be used to seal closed systems (gear boxes, electrical boxes, etc.). Acetic acid will corrode internal parts (bearings, contacts, etc.).
- LOCTITE® HIGH PERFORMANCE SILICONES ARE 8 TIMES MORE OIL RESISTANT THAN STANDARD RTV SILICONES. Standard RTV silicones should not be used to seal "Hot Oil" systems (oil pan, etc.). They swell and lose sealing ability.



STRENGTHEN KEYED ASSEMBLIES

KEYED ASSEMBLIES - STANDARD DUTY



ASSEMBLY

1. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
2. If necessary, spray all parts (I.D. and O.D.) with LOCTITE® SF 7649™ Primer N™.
3. Apply LOCTITE® 660™ Retaining Compound coating into keyway and on key.
4. Apply dab(s) of LOCTITE® 660™ Retaining Compound onto shaft opposite keyway or evenly spaced around shaft.
5. Assemble parts. Wipe off excess.
6. Apply LOCTITE® 660™ Retaining Compound dab to set screw.
7. Tighten set screw.
8. Allow 5-10 minutes prior to service.

Note:

- LOCTITE® 660™ Retaining Compound is NOT recommended for radial gaps exceeding 0.020" on shaft or keyway.
- See BADLY WALLOVED KEYWAY for procedure page 21.


DISASSEMBLY

1. Tap component and key with hammer.
2. Pull as usual.



STRENGTHEN KEYED ASSEMBLIES

KEYED ASSEMBLIES - HEAVY DUTY



ASSEMBLY

1. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
2. Apply a LOCTITE® **660™** Retaining Compound coating around shaft, into keyway, and on key.
3. Assemble parts. Wipe off excess.
4. Apply a LOCTITE® **660™** Retaining Compound dab to screw.
5. Tighten set screw.
6. Allow 30 minutes prior to service.

Note:

- If gap exceeds 0.005", use LOCTITE® SF 7649™ Primer N™ on appropriate area (shaft or keyway).
- LOCTITE® **660™** Retaining Compound is NOT recommended for radial gaps exceeding 0.020" on shaft or keyway.
- See BADLY WALLOVED KEYWAY for procedure page 21.


DISASSEMBLY

1. Tap component and key with hammer.
2. If necessary, apply localized heat (230°C for five minutes).
3. Pull while hot.



STRENGTHEN KEYED ASSEMBLIES

REPAIR BADLY WALLLOWED KEYWAY



1. Determine the gap width on each side of key.
2. Select and trim appropriate shim stock.
3. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
4. If necessary, spray all parts with LOCTITE® SF 7649™ Primer N™. Allow to dry.
5. Apply a LOCTITE® 66o™ Retaining Compound coating into keyway.
6. Install shims.
7. Assemble as required using LOCTITE® 66o™ Retaining Compound.
8. Allow 30-60 minute cure time.

Note:

- Minimize “gap fill” using shim stock.
- LOCTITE® 66o™ Retaining Compound is NOT recommended for lateral gaps exceeding 0.020”.
- Higher strengths are obtained by NOT using LOCTITE® SF 7649™ Primer N™ with small (0.002”-0.004”) gap, and allowing longer cure (4-24 hours).


EMERGENCY REPAIR ONLY!

Due to the nature of the damage, this should be considered a temporary repair until the unit can be replaced.



SHAFT MOUNTED ASSEMBLIES

REPAIR BADLY WORN SHAFT



1. Determine a minimum radial gap.
2. Select and trim appropriate sleeve to allow component slip fit.
3. Roughen sleeve O.D. with emery cloth.
4. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
5. Apply a LOCTITE® **638™** or LOCTITE® **66o™** Retaining Compound coating around the shaft.
6. Install sleeve.
7. Apply a coating of LOCTITE® **66o™** Retaining Compound to sleeve O.D.
8. Install component as required onto sleeved shaft.
9. Allow 30-60 minute cure.

Note:

- Minimize gap fill using shim stock or sleeve material.
- LOCTITE® **66o™** Retaining Compound is NOT recommended for lateral gaps exceeding 0.020".
- Higher strengths are obtained by NOT using LOCTITE® SF 7649™ Primer N™ with small (0.002"-0.004") Gap, and allowing longer cure (4-24 hours).


EMERGENCY REPAIR ONLY!

Due to the nature of the damage, this should be considered a temporary repair until the unit can be replaced.



SHAFT MOUNTED ASSEMBLIES

SLIP FIT - LIGHT DUTY



ORIGINAL

1. Machine shaft to 0.002" radial slip fit with 50-80 rms finish (second cut).
2. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
3. Spray all parts (I.D. and O.D.) with LOCTITE® SF 7649™ Primer N™.
4. Apply LOCTITE® **660™/641™** Retaining Compound dabs around shaft at engagement area.
5. Assemble parts. Do not rotate.
6. Wipe off excess.
7. Allow ten minutes prior to service.

WORN SHAFT


Follow directions above except:

1. Determine radial gap.
 2. If radial gap exceeds 0.005", LOCTITE® SF 7649™ Primer N™ must be used.
 3. Take steps to maintain concentricity with large gaps.
 4. Larger gaps require longer cure times (30-60 minutes).
 5. LOCTITE® **660™** Retaining Compound is NOT recommended for radial gaps exceeding 0.020".
 6. See procedure for BADLY WORN SHAFT page 22.
- Note:** LOCTITE® **660™** Retaining Compound is very fast fixturing (30 seconds or less) with LOCTITE® SF 7649™ Primer N™.



SHAFT MOUNTED ASSEMBLIES

SLIP FIT - HEAVY DUTY



ORIGINAL

1. Machine shaft to 0.002" radial slip fit with 50-80 rms finish (second cut).
2. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
3. Do NOT use LOCTITE® SF 7649™ Primer N™.
4. Apply a LOCTITE® **66o™** Retaining Compound coating around shaft and engagement area.
5. Assemble parts with rotating motion.
6. Wipe off excess.
7. Allow 2 hours prior to service.

WORN SHAFT

Follow directions above except:

1. Determine radial gap.
2. If radial gap exceeds 0.005", LOCTITE® SF 7649™ Primer N™ must be used.
3. Take steps to maintain concentricity with large gaps.
4. Larger gaps require longer cure times (30-60 minutes).
5. LOCTITE® **66o™** Retaining Compound is NOT recommended for radial gaps exceeding 0.020".
6. See procedure for BADLY WORN SHAFT page 22.

MAXIMUM STRENGTH

1. Same as above, except use LOCTITE® **638™** Retaining Compound with LOCTITE® SF 7471™ Primer T™ or no primer.
2. Allow 4-24 hours to cure.

MAXIMUM TEMPERATURE (200°C continuous)

1. Same as above, except use LOCTITE® **62o™** Retaining Compound with LOCTITE® SF 7471™ Primer T™.


DISASSEMBLY

1. Pull as usual.
2. If necessary, apply localized heat (230°C for 5 minutes). Pull while hot.



SHAFT MOUNTED ASSEMBLIES

PRESS FIT



STANDARD

1. Clean shaft O.D. and Component I.D.
2. Apply a bead of LOCTITE® 609™ (603™)* Retaining Compound to circumference of shaft at leading edge of insertion or leading area of engagement.

Note:

- Retaining compound will always be squeezed to the outside when applied to shaft.
- Do NOT use with LOCTITE® Anti-Seizes or similar product.

3. Press as usual. Wipe off excess.
4. No cure time required.

Note: LOCTITE® 609™ (603™)* Retaining Compound is used due to low viscosity and Wetting properties.

TANDEM MOUNT


1. Apply retaining compound to bore of inside component.
2. Continue assembly as above.

* Worldwide or Application-Specific Alternative



SHAFT MOUNTED ASSEMBLIES

SHRINK FIT



ASSEMBLY


1. Clean the shaft O.D. and component I.D.
2. Cool the shaft to cause contraction, or heat the component to cause expansion.
3. Apply a brush film of LOCTITE® 620™ Retaining Compound to the shaft or lower temperature part.
4. Install component and allow temperatures to equilibrate.
5. Wipe off excess.

Note: LOCTITE® 620™ Retaining Compound will add lubricity for easier assembly while sealing and protecting the bond area from environmental exposure and filling gaps for a more complete contact area.



HOUSED COMPONENTS

SLIP FIT - LIGHT DUTY



ORIGINAL

1. Select component to fit shaft.
2. Machine to reduce component O.D. or increase housing I.D. to permit approximate 0.002" - 0.004" diametral slip fit.
3. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser and spray with LOCTITE® SF 7649™ Primer N™.
4. Apply several LOCTITE® 660™ Retaining Compound dabs to component O.D.
5. Install component. Do not rotate.
6. Wipe off excess.
7. Allow five minutes prior to service.

WORN


Procedures identical to original slip fit, except:

1. Determine the maximum radial gap.
2. If the maximum gap exceeds 0.005", LOCTITE® SF 7649™ Primer N™ must be used.
3. Take steps to maintain concentricity on large gaps.
4. Large gaps require longer cure times (30-60 minutes).
5. LOCTITE® 660™ Retaining Compound is NOT recommended for radial gaps exceeding 0.020".
6. See procedure for BADLY WORN HOUSING page 28.



HOUSED COMPONENTS

SLIP FIT - HEAVY DUTY



ORIGINAL - RECOMMENDED ASSEMBLY

1. Select component to fit shaft.
2. Machine to reduce component O.D. or housing I.D. to permit approximate 0.002" - 0.004" diametral slip fit.
3. Clean all parts with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
4. Do NOT use LOCTITE® SF 7649™ Primer N™.
5. Apply a LOCTITE® **66o™** Retaining Compound coating to component O.D.
6. Install component with twisting motion.
7. Wipe off excess.
8. Allow 2 hours prior to service.

WORN - RECOMMENDED ASSEMBLY

Procedures identical to original slip fit, except:

1. Determine the maximum radial gap.
2. If the maximum radial gap exceeds 0.005", then LOCTITE® SF 7649™ Primer N™ must be used.
3. Take steps to maintain concentricity on large gaps.
4. Large gaps require longer cure times (30-60 minutes).
5. LOCTITE® **66o™** Retaining Compound is not recommended for radial gaps exceeding 0.020".
6. See procedure for BADLY WORN HOUSING page 29.


DISASSEMBLY

1. Pull as usual.
2. If necessary, apply localized heat (230°C for five minutes).
3. Pull while hot.



HOUSED COMPONENTS

REPAIRING BADLY WORN HOUSING



RECOMMENDED ASSEMBLY

1. Roughen housing I.D. with emery cloth.
2. Clean the housing I.D. with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
3. Clean the component O.D. and apply Silicone Oil / Release Agent. Allow to dry.
4. Prepare (mix) LOCTITE® EA 3478 Superior Metal.
5. Apply a light coating of LOCTITE® EA 3478 Superior Metal to component O.D.
6. Position the component in housing. Maintain concentricity.
7. Pack LOCTITE® EA 3478 Superior Metal into gaps and voids.
8. Wipe off excess.
9. Allow to cure 30 minutes.
10. Pull component.
11. Clean the release compound from component O.D.
12. Roughen the housing I.D. and clean thoroughly.
13. Assemble with LOCTITE® 660™ Retaining Compound as required.
14. Recommended for light duty service.


EMERGENCY REPAIR ONLY!

Due to the nature of the damage, this should be considered a temporary repair until the unit can be replaced.




HOUSED COMPONENTS

COMPONENT CENTERING



EXCESSIVE / EVEN WEAR

1. Position the component in bore.
2. Select three equilateral mounting points.
3. Determine the radial gap at those points.
4. Select appropriate shim stock.
5. Cut three pieces approx. 1.8" wide to fit bore depth.
6. Bond the shims to bore at mounting points using LOCTITE® 380™ (401™)* Instant Adhesive.
7. Assemble as per instructions page 28.



EXCESSIVE / UNEVEN WEAR

1. Position the component in bore.
2. Select three equilateral mounting points.
3. Determine the radial gap at those points.
4. Select and cut appropriate shim stock for each point.
5. Bond the shims to bore at mounting points using LOCTITE® 380™ (401™)* Instant Adhesive.
6. Assemble as per instructions on page 29.

EMERGENCY REPAIR ONLY!


Due to the nature of the damage, this should be considered a temporary repair until the unit can be replaced.

* Worldwide or Application-Specific Alternative



HOUSED COMPONENTS

SEALING/RETAINING - METALLIC SEAL



1. Clean the housing I.D. and seal O.D. with LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser.
2. Spray both the housing and seal with LOCTITE® SF 7649™ Primer N™.
3. Apply a bead of LOCTITE® **243™** Threadlocker to the leading edge of metallic seal O.D.
Note: Virtually any LOCTITE® Threadlocking product will work here. Medium strength liquid is recommended due to normal gap and strength requirement.
4. Install as usual.
5. Wipe off excess.
6. Allow to cure 30 minutes.
Note:
 - LOCTITE® **243™** Threadlocker is normally used with worn seal housings to prevent Leakage or slippage.
 - It is not generally necessary to remove pre-applied sealant from seal O.D.



RETAINING COMPOUNDS

LOCTITE® RETAINING COMPOUNDS QUICK SELECTOR

Application	LOCTITE® Product	LOCTITE® Primer
Shaft Mount - Press Fit		
Medium Strength	609™ (603™)* Retaining Compound	None
Low Strength	641™ Retaining Compound	T™
Shaft Mount - Press Fit		
Small Gap (0.005" Radial max.)	609™ (603™)* Retaining Compound	N™
Larger Gap (0.020" Radial max.)	660™ Retaining Compound	N™
High Strength (0.01" Radial max.)	638™ Retaining Compound	T™
Maximum Temperature (204°C) (0.008" Radial max.)	620™ Retaining Compound	T™
Low Strength (0.006" Radial max.)	641™ Retaining Compound	T™
Housing Mount - Press Fit		
Medium Strength	609™ (603™)* Retaining Compound	NONE
Low Strength	641™ Retaining Compound	T™
Medium Strength	243™ Threadlocker	NONE
Housing Mount - Slip Fit		
High Strength	638™ Retaining Compound	NONE
High Strength	660™ Retaining Compound	N™
Low Strength	641™ Retaining Compound	T™
Medium Strength	243™ Threadlocker	N™

Note:

- Softer metals (Aluminum, Bronze, etc.) provide lower shear strengths than ferrous components.
- Excessive gap reduces shear strengths.
- Ideal surface finish - 50 to 80 rms.


Refer to Technical Data Sheets for more information.

* Worldwide or Application-Specific Alternative




BONDING


PROPER JOINT DESIGN




LAP/OVERLAP
GOOD




JOGGLE LAP
GOOD




BUTT
FAIR/POOR



SCARF
FAIR




SINGLE STRAP
GOOD




DOUBLE STRAP
BEST


TYPES OF STRESSES




TENSILE
FAIR




COMPRESSIVE
GOOD



CLEAVAGE
POOR



SHEAR
GOOD



PEEL
POOR


DESIGN GUIDELINES

1. Maximize shear/minimize peel and cleavage.
2. Maximize compression/minimize tensile.
3. Joint width more important than overlap.




BONDING

O-RING MARKING



1. Cut the starting end of the cord stock with a clean razor blade. Ensure the cut is clean and square. Do not touch the clean cut end.
2. Measure cord stock to appropriate length. For precise measurement, use LOCTITE® O-Ring Tool or the ruler provided in the LOCTITE® O-Ring Making Kit.
3. Cut the measured end of the cord stock with a clean razor blade. Ensure the cut is clean and square to optimize bond area.
4. Apply one drop of LOCTITE® **406™** Instant Adhesive and mate the two ends of the cord stock.

BONDING METAL LABEL




1. Clean surface.
2. Spray LOCTITE® SF **7075™** Activator onto main part. Let dry for two minutes.
3. Apply LOCTITE® AA **324™** Structural Adhesive onto back of label.
4. Press label onto activated surface and hold for a few seconds.
5. Reaches handling strength in 5 minutes. Full cure in 24 hours.




BONDING

FILLING CRACKS



1. Clean surface.
2. Mix LOCTITE® PC **3473** Fast Steel Putty according to package directions.
3. Spread mixed material over crack.
4. Sets in 5 minutes, full cure in 8 hours.
5. For maximum protection, a piece of material can be applied over the top of the crack to spread the load after applying the mixed adhesive. The adhesive will hold it in place.

STRUCTURAL BONDING



1. Prepare the surface using LOCTITE® SF 7070 ODC-Free Cleaner and Degreaser.
2. Attach mix nozzle to the LOCTITE® **H3151™** Structural Adhesive cartridge.
3. Dispense 50 mm (2") of material to prime nozzle.
4. Apply a continuous bead of adhesive in the area you want to patch and/or seal.
5. Assemble patch using pneumatic pins or rivets, or run screws to hold parts together while the adhesive reaches full cure.
6. Equipment can be back in operation after 24 hours.



BONDING

ADHESIVE QUICK SELECTOR

Product	Typical Application
<p>LOCTITE® 454™ Instant Adhesive - A surface insensitive gel instant adhesive for common and “difficult-to-bond” materials. Excellent for porous materials, overhead applications and large gaps.</p>	<p>Plastics, rubber, foam, ceramics, felt, cork, wood, etc.</p>
<p>LOCTITE® 406™ Instant Adhesive - Particularly suited for bonding rubbers & plastics. A must for every tool box for general maintenance & repair. Makes O-rings instantly. Wicking viscosity for tight bond lines.</p>	<p>General purpose bonding, makes O-ring.</p>
<p>LOCTITE® SF 7452™ Accelerator or SF 712™ Activator - A spray mist for fast surface curing of all instant adhesives.</p>	<p>Tacking jumper wires on PC boards, strain relief, temporary jig placement, etc.</p>
<p>LOCTITE® SF 770™ Primer - Permits bonding of polyethylene, polystyrene, etc. Allow 24 hour adhesive cure time for maximum strength.</p>	<p>Wear pads, bumpers, buckets, etc</p>
<p>LOCTITE® AA 324 Structural Adhesive - A no-mix structural acrylic adhesive used for general purpose, severe environments and less than optimum cleanliness applications. Works on most surfaces except rubber and polyethylene.</p>	<p>Sheet metal, glass, fiberglass, composites, wood, etc.</p>
<p>LOCTITE® PC 3473 Fast Steel Putty - A two-part putty used in rough service, severe environments and for emergency repair.</p>	<p>Casting or case repair, sealing punctures, pin holes, etc.</p>



BONDING

GUIDE TO SUCCESSFUL BONDING

I. JOB EVALUATION - Answer These Questions.

- A. What materials are to be bonded? What kind of rubber, plastic, etc.? Porous? Slick? Rough?
- B. What kind of service? Operating temperature? Impact? Moisture or water exposure?
- C. What kind of stresses? Avoid peel or cleavage!
- D. Is gap filling or bridging needed? How much?
- E. What cure speed or "return to service" time is needed?

II. ADHESIVE SELECTION (See page 35.)

III. SURFACE PREPARATION

1. Part must be clean. No oil. No grease. No residue.
2. Remove paint from bond area for maximum strength.
3. Roughen smooth surfaces with emery cloth.
4. Treat selected "difficult-to-bond" materials as directed:
 - a. Polyethylene, etc. - Use LOCTITE® SF 770™ Primer or 793™ Primer.
 - b. PTFE - Use appropriate etching agent.
5. Alcohol wipe parts cleaned with water-based "safety" cleaners.

IV. APPLICATION TECHNIQUES/TIPS

- A. Read and follow adhesive package instructions.
- B. Use the minimum amount of adhesive to one part only.
Apply activator (if required) to other part.
- C. Avoid "jiggling" mated parts. Apply clamp pressure if possible.
- D. Allow maximum cure time possible. See technical data for recommended cure times.


V. QUESTIONS?

Call Henkel Technical Services. See back cover for the nearest Henkel office in your area.



CLEANING

GENERAL PURPOSE PARTS CLEANING



In general, LOCTITE® SF **7840** Natural Blue Biodegradable Cleaner & Degreaser cleaning effectiveness is enhanced by:

- a. Higher concentrations of LOCTITE® SF **7840** Natural Blue Biodegradable Cleaner & Degreaser;
- b. Longer cleaner on-part times;
- c. Dilution with warm water (65°C to 82°C);
- d. Agitation of parts or scrubbing.

DIRECTIONS

1. Dilute LOCTITE® SF **7840** Natural Blue Biodegradable Cleaner & Degreaser concentrate with water to most economical/effectiveness level. See package labels for suggested ratios.
2. Spray, dip or wipe dilution onto parts or surface to be cleaned.
3. Soak parts or scrub (if needed).
4. Flush soil/cleaner mixture off of parts or surfaces with water.
5. Disposal: LOCTITE® SF **7840** Natural Blue Biodegradable Cleaner & Degreaser contains no hazardous Ingredients. It should be disposed of in accordance with state and local regulations and will not harm sewage treatment microorganisms. Once LOCTITE® SF **7840** Natural Blue Biodegradable Cleaner & Degreaser is mixed with hazardous waste, it must be treated as hazardous waste and disposed of accordingly.

Note: LOCTITE® SF 7070 ODC-Free Cleaner & Degreaser is recommended for cleaning substrates before LOCTITE® machinery adhesive use.



RUSTPROOFING

OPTIMUM USE OF LOCTITE® SF 7625 RUST TREATMENT

SURFACE PREPARATION - OLD STEEL:

Loose or “flaky” rust must be removed. Only conversion of firmly bonded rust will result in durable protection. Oil, grease, old paint, mill scale, form oil, fingerprints and water soluble surfaces and chlorides must be removed to allow LOCTITE® SF 7625 Rust Treatment to react with rust.

Loose rust, mill scale and oil paint should be removed preferably by power Wirebrushing, followed by rinsing with water to remove powder and solubles. Manual wirebrushing, chipping, scraping and particularly rotopeening can also be used. Oil, grease, form oil and fingerprints should be removed before loose rust. Ideal surfaces will show light rust as well as bare metal surfaces.

RUST CONVERSION TIME AND APPEARANCE:

Two coats of LOCTITE® SF 7625 Rust Treatment are recommended.

On lightly rusted steel (that has been wirebrushed), the first coat will start to develop a violet color within 60 seconds. This will become satin to flat black in appearance. The second coat should dry to a satin black appearance.

On heavily rusted steel (that has been wirebrushed), the first coat should develop a purple-black color within seconds. The second coat should dry to a black color with gloss varying from flat to satin. The second coat should be applied within 15-30 minutes of the first coat.

APPLICATION CONDITIONS:

LOCTITE® SF 7625 Rust Treatment may be applied when surface and air is between 10°C minimum and rising and 32°C maximum and falling. Reaction is slower at lower temperatures. If temperature is too hot, film may surface dry and bubble. High humidity is beneficial; it slows drying but assists rust conversion. LOCTITE® SF 7625 Rust Treatment should not be applied in conditions of condensing humidity (e.g. fog, dew), on ice, in rain or in heavy sea (salt) spray atmospheres. Steel surface may be damp but not wet (i.e. continuous visible film of water). DO NOT APPLY LOCTITE® SF 7625 RUST TREATMENT TO SURFACES IN DIRECT SUNLIGHT.

APPLICATION EQUIPMENT METHODS:

LOCTITE® SF 7625 Rust Treatment may be applied by brush, roller, or spray. Brush or roller is suitable for small areas. Avoid sags and ridges and keep edges wet by coating about a square yard at a time. Roll away from previously coated area then roll back. Do not pour unused material back into the original container. NEVER add solvents to LOCTITE® SF 7625 Rust Treatment. Spray application is recommended for larger areas. Airless spray equipment is faster, and provides more effective conversion due to improved surface penetration. Conventional air-spray equipment may be used, but LOCTITE® SF 7625 Rust Treatment may require thinning up to 10% with water for proper spraying.



TROUBLESHOOTING

CHECKLIST

1. What type failure is occurring? Has the application worked before?
2. Was proper and adequate adhesive/sealant used?
3. Was proper and adequate primer/activator used?
4. Do service conditions exceed the capability of the adhesive/sealant?
 - (a) operating temperature
 - (b) excessive pressure too soon
 - (c) fluid compatibility
 - (d) impact on environment (instant adhesives)
5. Were parts adequately cleaned prior to applying adhesive?

Note: If adhesive failure, is cured residue on one or both parts? If one part is bare, Check that part for contamination.
6. Were proper assembly techniques utilized?
7. Was adhesive/sealant allowed adequate cure time prior to service?
8. Do assembly/part conditions exceed capability of the adhesive/sealant?
 - (a) excessive gaps
 - (b) component materials
 - (c) improper joint design
 - (d) inadequate clamping/fixturing
9. If additional assistance is required, please contact us at addresses on back cover.

LIMITATION OF WARRANTY

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof.

In light of the foregoing, HENKEL SPECIFICALLY DISCLAIMS ALL WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE ARISING FROM SALE OR USE OF HENKEL'S PRODUCTS.

HENKEL SPECIFICALLY DISCLAIMS ANY LIABILITY FOR CONSEQUENTIAL OR INCIDENTAL DAMAGES OF ANY KIND, INCLUDING LOST PROFITS. The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel patents which may cover such processes or compositions. We recommend that each prospective user test the proposed application to determine its suitability for the purposes intended prior to incorporating any product or application in its manufacturing process using this data as a guide. Some products may be covered by one or more domestic or foreign patents or patent applications.

FLUID COMPATIBILITY CHART

for metal threaded fittings sealed with LOCTITE® Sealants

LIQUIDS, SOLUTIONS & SUSPENSIONS

LEGEND:

- Use LOCTITE® #592, 567, 565, 569, 545, 580, 571, 242, 577, 572, 542, 565, 545, 243
- † Use LOCTITE® #277, 271, 554, 270, 277, 554
- Not Recommended
- <10% (same as I)
- >10% (same as †)
- <5% (same as I)
- * <5% (same as †)

Abrasive Coolant	•	Ammonium Fluorosilicate	•	Brine Cold	•	Chlorinated Paperstock	•
Acetaldehyde	•	Ammonium Formate	•	Bromine Solution	†	Chlorinated Solvents	•
Acetate Solvents	•	Ammonium Hydroxide	■	Butadiene	•	Chlorinated Sulphuric Acids	■
Acetimid	•	Ammonium Hyposulfite	•	Butyl Acetate	•	Chlorinated Wax	•
Acetic Acid	•	Ammonium Iodide	•	Butyl Alcohol	•	Chlorine Dioxide	■
Acetic Acid	□	Ammonium Molybdate	•	Butyl Amine	•	Chlorine Liquid	■
Acetic Acid - glacial	•	Ammonium Nitrate	•	Butyl Cellosolve §	•	Chlorine Dry	■
Acetic Anhydride	•	Ammonium Oxalate	•	Butyl Chloride	•	Chloroacetic Acid	□
Acetone	•	Ammonium Persulfate	•	Butyl Ether - Dry	•	Calcium Silicate	•
Acetyl Chloride	•	Ammonium Phosphate	•	Butyl Lactate	•	Calcium Sulfamate	•
Acetylene (Liquid Phase)	•	Ammonium Picrate	•	Butyral Resin	•	Calcium Sulfate	•
Acid Clay	•	Ammonium Sulfate	•	Butyraldehyde	•	Calcium Sulfite	•
Acrylic Acid	•	Ammonium Sulfate Scrubber	•	Butyric Acid	□	Camphor	•
Acrylonitrile	•	Ammonium Sulfide	•	Cadmium Chloride	•	Carbitol	•
Activated Alumina	•	Ammonium Thiocyanate	•	Cadmium Plating Bath	•	Carbolic Acid (phenol)	□
Activated Carbon	•	Amyl Acetate	•	Cadmium Sulfate	•	Carbon Bisulfide	•
Activated Silica	•	Amyl Amine	•	Calcium Acetate	•	Carbon Black	•
Alcohol-Allyl	•	Amyl Chloride	•	Calcium Bisulfate	•	Carbon Tetrachloride	•
Alcohol-Amyl	•	Aniline	•	Calcium Carbonate	•	Carbonic Acid	□
Alcohol-Benzyl	•	Aniline Dyes	•	Calcium Chlorate	•	Carbowax §	•
Alcohol-Butyl	•	Anodizing Bath	•	Calcium Chloride	•	Carboxymethyl Cellulose	•
Alcohol-Ethyl	•	Antichlor Solution	•	Calcium Chloride Brine	•	Carnauba Wax	•
Alcohol-Furfuryl	•	Antimony Acid Salts	•	Calcium Citrate	•	Casein	•
Alcohol-Hexyl	•	Antimony Oxide	•	Calcium Ferrocyanide	•	Casein Water Paint	•
Alcohol-Isopropyl	•	Antioxidant Gasoline	•	Calcium Formate	•	Celite	•
Alcohol-Methyl	•	Aqua Regia	■	Calcium Hydroxide	•	Cellosolve §	•
Alcohol-Propyl	•	Argon	•	Calcium Lactate	•	Cellulose Pulp	•
Alum-Ammonium	•	Armeen §	•	Calcium Nitrate	•	Cellulose Xanthate	•
Alum-Chrome	•	Arochlor §	•	Calcium Phosphate	•	Cement Dry/Air Blown	•
Alum-Potassium	•	Aromatic Gasoline	•	Calcium Silicate	•	Cement Grout	•
Alum-Sodium	•	Aromatic Solvents	•	Calcium Sulfamate	•	Cement Slurry	•
Alumina	•	Arsenic Acid	•	Calcium Sulfate	•	Ceramic Enamel	•
Aluminum Acetate	•	Asbestos Slurry	•	Calcium Sulfite	•	Ceric Oxide	•
Aluminum Bicarbonate	•	Ash Slurry	•	Camphor	•	Chalk	•
Aluminum Bifluoride	•	Asphalt Emulsions	•	Carbitol	•	Chemical Pulp	•
Aluminum Chloride	•	Asphalt Molten	•	Carbolic Acid (phenol)	□	Chestnut Tanning	•
Aluminum Sulfate	•	Bagasse Fibers	•	Carbon Bisulfide	•	China Clay	•
Ammonia Anhydrous	■	Barium Acetate	•	Carbon Black	•	Chloral Alcoholate	•
Ammonia Solutions	■	Barium Carbonate	•	Carbon Tetrachloride	•	Chloramine	•
Ammonium Bisulfite	•	Barium Chloride	•	Carbonic Acid	□	Chlorinated Hydrocarbons	•
Ammonium Borate	•	Barium Hydroxide	□	Carbowax §	•	Chlorinated Paperstock	•
Ammonium Bromide	•	Barium Sulfate	•	Carboxymethyl Cellulose	•	Chlorinated Solvents	•
Ammonium Carbonate	•	Battery Acid	□	Carnauba Wax	•	Chlorinated Sulphuric Acids	■
Ammonium Chloride	•	Battery Diffuser Juice	•	Casein	•	Chlorinated Wax	•
Ammonium Chromate	•	Bauxite (See Alumina)	•	Casein Water Paint	•	Chlorine Dioxide	■
Ammonium Fluoride	•	Bentonite	•	Celite	•	Chlorine Liquid	■
		Benzaldehyde	•	Cellosolve §	•	Chlorine Dry	■
		Benzene	•	Cellulose Pulp	•	Chloroacetic Acid	□
		Benzene Hexachloride	•	Cellulose Xanthate	•	Chlorobenzene Dry	•
		Benzene in Hydrochloric Acid	•	Cement Dry/Air Blown	•	Chloroform Dry	•
		Benzoic Acid	•	Cement Grout	•	Chloroformate Methyl	•
		Benztotriazole	•	Cement Slurry	•	Chlorosulfonic Acid	■
		Beryllium Sulfate	•	Ceramic Enamel	•	Chrome Acid Cleaning	□
		Bicarbonate Liquor	•	Ceric Oxide	•	Chrome Liquor	□
		Bilge Lines	•	Chalk	•	Chrome Plating Bath	□
		Bleach Liquor	•	Chemical Pulp	•	Chromic Acid 10%	•
		Bleached Pulps	•	Chestnut Tanning	•	Chromic Acid 50% (cold)	■
		Borax § Liquors	•	China Clay	•	Chromic Acid 50% (hot)	■
		Boric Acid	•	Chloral Alcoholate	•	Chromium Acetate	•
		Brake Fluids	•	Chloramine	•	Chromium Chloride	•
		Brine Chlorinated	•	Chlorinated Hydrocarbons	•	Chromium Sulfate	•

FLUID COMPATIBILITY CHART

for metal threaded fittings sealed with LOCTITE® Sealants

LIQUIDS, SOLUTIONS & SUSPENSIONS

Classifier	•	Ethyl Bromide	•	Glycol Amine	•	Kelp Slurry	•
Clay	•	Ethyl Cellosolve §	•	Glycolic Acid	•	Kerosene	•
Coal Slurry	•	Ethyl Cellosolve Slurry §	•	Glyoxal	•	Kerosene Chlorinated	•
Coal Tar	•	Ethyl Formate	•	Gold Chloride	•	Ketone	•
Cobalt Chloride	•	Ethyl Silicate	•	Gold Cyanide	•	Lacquer Thinner	•
Copper Ammonium Formate	•	Ethylene Diamine	•	Granodine	•	Lactic Acid	•
Copper Chloride	•	Ethylene Dibromide	•	Grape Pomace Graphite	•	Lapping Compound	•
Copper Cyanide	•	Ethylene Dichloride	•	Grease Lubricating	•	Latex-Natural	•
Copper Liquor	•	Ethylene Glycol	•	Green Soap	•	Latex-Synthetic	•
Copper Naphthenate	•	Ethylenediamine Tetramine	•	Grinding Lubricant	•	Latex Synthetic Raw	•
Copper Plating, Acid Process	•	Fatty Acids	•	Grit Steel	•	Laundry Wash Water	•
Copper Plating, Alk. Process	•	Fatty Acids Amine	•	Gritty Water	•	Laundry Bleach	•
Copper Sulfate	•	Fatty Alcohol	•	Groundwood Stock	•	Laundry Blue	•
Core Oil	•	Ferric-Floc	•	GRS Latex	•	Laundry Soda	•
Corundum	•	Ferric Chloride	•	Gum Paste	•	Lead Arsenate	•
Creosote	•	Ferric Nitrate	•	Gum Turpentine	•	Lead Oxide	•
Creosote-Cresylic Acid	•	Ferric Sulfate	•	Gypsum	•	Lead Sulfate	•
Cyanide Solution	•	Ferrocene-Oil Sol	•	Halane Sol	•	Lignin Extract	•
Cyanuric Chloride	•	Ferrous Chloride	•	Halogen Tin Plating	•	Lime Slaked	•
Cyclohexane	•	Ferrous Oxalate	•	Halowax §	•	Lime Sulfur Mix	•
Cylinder Oils	•	Ferrous Sulfate%o	•	Harvel-Trans oil	•	Liquid Ion Exchange	•
De-Ionized Water	•	Ferrous Sulfate (Sat)	•	Heptane	•	Lithium Chloride	•
De-Ionized Water Low Conductivity	•	Fertilizer Sol	•	Hexachlorobenzene	•	LOX (Liquid oz)	■
Detergents	•	Flotation Concentrates	•	Hexadiene	•	Ludox	•
Developer, photographic	•	Fluoride Salts	•	Hexamethylene Tetramine	•	Lye	■
Dextrin	•	Fluorine, Gaseous or Liquid	•	Hexane	•	Machine Coating Color	•
Diacetone Alcohol	•	Fluorolube	•	Hydrazine	•	Magnesite Slurry	•
Diammonium Phosphate	•	Fluosilic Acid	•	Hydrazine Hydrate	•	Magnesite	•
Diamylamine	•	Flux Soldering	•	Hydrobromic Acid	□	Magnesium Bisulfite	•
Diatomaceous Earth Slurry	•	Fly Ash Dry	•	Hydrochloric Acid	•	Magnesium Carbonate	•
Diazo Acetate	•	Foam Latex Mix	•	Hydrocyanic Acid	□	Magnesium Chloride	•
Dibutyl Phthalate	•	Foamite	•	Hydrofluoric Acid	■	Magnesium Hydroxide	•
Dichlorophenol	•	Formaldehyde (cold)	•	Hydrogen Peroxide (dil)	•	Magnesium Sulfate	•
Dichloro Ethyl Ether	•	Formaldehyde (hot)	†	Hydrogen Peroxide (con)	†	Maleic Acid	•
Dicyandamide	•	Formic Acid (Dil cold)	•	Hydroquinone Sol	•	Maleic Anhydride	•
Dielectric Fluid	•	Formic Acid (Dil hot)	†	Hydroquinone	•	Manganese Chloride	•
Diester Lubricants	•	Formic Acid (cold)	•	Hydroxyacetone	•	Manganese Sulfate	•
Diethyl Ether Dry	•	Formic Acid (hot)	†	Hypo	•	Melamine Resin	•
Diethyl Sulfate	•	Freon §	†	Hypochlorous Acid	•	Menthhol	•
Diethylamine	•	Fuel Oil	•	Ink	•	Mercaptans	•
Diethylene Glycol	•	Fuming Nitric Red	■	Ink in Solvent-Printing	•	Mercuric Chloride	•
Diglycolic Acid	•	Fuming Sulfuric	■	Iodine in Alcohol	•	Mercuric Nitrate	•
Dimethyl Formamide	•	Fuming Oleum	■	Iodine-Potassium Iodide	•	Mercury	•
Dimethyl Sulfoxide	•	Furfural	•	Iodine Solutions	•	Mercury Dry	•
Dioxane Dry	•	Gallic Acid * Gallium Sulfate	•	Ion Exchange Service	•	Methane	•
Dioxidene	•	Gasoline-Acid Wash	•	Ion Exclusion Glycol	•	Methyl Alcohol	•
Dipentene - Pinene	•	Gasoline-Alk. Wash	•	Irish Moss Slurry	•	Methyl Acetate	•
Diphenyl	•	Gasoline Aviation	•	Iron Ore Taconite	•	Methyl Bromide	•
Distilled Water (Industrial)	•	Gasoline Copper Chloride	•	Iron Oxide	•	Methyl Carbitol	•
Dowtherm §	•	Gasoline Ethyl	•	Isobutyl Alcohol	•	Methyl Cellosolve §	•
Drying Oil	•	Gasoline Motor	•	Isobutyraldehyde	•	Methyl Chloride	•
Dust-Flue (Dry)	•	Gasoline Sour	•	Isooctane	•	Methyl Ethyl Ketone	•
Dye Liquors	•	Gasoline White	•	Isopropyl Alcohol	•	Methyl Isobutyl Ketone	•
Emery - Slurry	•	Gluconic Acid	•	Isocyanate Resin	•	Methyl Lactate	•
Emulsified Oils	•	Glue-Animal Gelatin	•	Isopropyl Acetate	•	Methyl Orange	•
Enamel Frit Slip	•	Glue-Plywood	•	Isopropyl Ether	•	Methylamine	•
Esters General	•	Glutamic Acid	•	Itaconic Acid	•	Methylene Chloride	•
Ethyl Acetate	•	Glycerine Lye-Brine	■	Jet Fuels	•	Mineral Spirits	•
Ethyl Alcohol	•	Glycerol	•	Jeweler's Rouge	•	Mixed Acid, Nitric/Sulfuric	■
Ethyl Amine	•	Glycine	•	Jig Table Slurry	•	Monochloroacetic Acid	•
		Glycine Hydrochloride	•	Kaolin-China Clay §	•	Morpholine	•

FLUID COMPATIBILITY CHART

for metal threaded fittings sealed with LOCTITE® Sealants

LIQUIDS, SOLUTIONS & SUSPENSIONS

Mud	•	Paper Stocks, fine	•	Potassium Alum. Sulfate	•	Silicone Fluids	•
Nalco Sol.	•	Paradichlorobenzene	•	Potassium Bromide	•	Silver Cyanide	•
Naphtha	•	Paraffin Molten	•	Potassium Carbonate	•	Silver Iodide-Aqu.	•
Naphthalene	•	Paraffin Oil	•	Potassium Chlorate	•	Silver Nitrate	•
Naval Stores Solvent	•	Paraformaldehyde	•	Potassium Chloride Sol	•	Size Emulsion	•
Nematocide	•	Pectin Solution Acid	•	Potassium Chromate	•	Skelly Solve E, L	•
Neoprene Emulsion	•	Pentachlorethane	•	Potassium Cyanide Sol.	•	Slate to 400 Mesh	•
Neoprene Latex	•	Pentaerythritol Sol.	•	Potassium Dichromate	•	Soap Lye	■
Nickel Acetate	•	Perchlorethylene (Dry)	•	Potassium Ferricyanide	•	Soap Solutions (Stearates)	•
Nickel Ammonium Sulfate	•	Perchloric Acid	□	Potassium Hydroxide	■	Soap Stone Air Blown	•
Nickel Chloride	•	Perchloromethyl Mercaptan	•	Potassium Iodide	•	Soda Pulp	•
Nickel Cyanide	•	Permanganic Acid	■	Potassium Nitrate	•	Sodium Acetate	•
Nickel Fluoborate	•	Persulfuric Acid	■	Potassium Perchlorate	•	Sodium Acid Fluoride	•
Nickel Ore Fines	•	Petroleum Ether	•	Potassium Permanganate	•	Sodium Aluminate	•
Nickel Plating Bright	•	Petroleum Jelly	•	Potassium Persulfate	•	Sodium Arsenate	•
Nickel Sulfate	•	Phenol Formaldehyde Resins	•	Potassium Phosphate	•	Sodium Benzene Sulfonate	•
Nicotinic Acid	□	Phenol Sulfonic Acid	•	Potassium Silicate	•	Sodium Bichromate	•
Nitrate Sol.	•	Phenolic Glue	•	Potassium Sulfate	•	Sodium Bisulfite	•
Nitration Acid(s)	■	Phloroglucinol	•	Potassium Xanthate	•	Sodium Bromide	•
Nitric Acid	■	Phosphate Ester	•	Press Board Waste	•	Sodium Carbonate	•
Nitric Acid10%	□	Phosphatic Sand	•	Propionic Acid	•	Sodium Chlorate	•
Nitric Acid 20%	↑	Phosphoric Acid 85% hot	■	Propyl Alcohol	•	Sodium Chlorite	•
Nitric Acid Anhydrous	■	Phosphoric Acid 85% cold	↑	Propyl Bromide	•	Sodium Cyanide	•
Nitric Acid Fuming	■	Phosphoric Acid 50% hot	↑	Propylene Glycol	•	Sodium Ferricyanide	•
Nitro Aryl Sulfonic Acid	•	Phosphoric Acid 50% cold	↑	Pumice	•	Sodium Formate	•
Nitrobenzene-Dry	•	Phosphoric Acid 10% cold	•	Pyranol	•	Sodium Glutamate	•
Nitrocellulose	•	Phosphoric Acid 10% hot	↑	Pyridine	•	Sodium Hydrogen Sulfate	•
Nitrofurane	•	Phosphorous Molten	•	Pyrogallic Acid	•	Sodium Hydrosulfite	•
Nitroguanidine	•	Phosphotungstic Acid	•	Pyrogen Free Water	•	Sodium Hydrosulfide	•
Nitroparaffins-Dry	•	Photographic Sol.	•	Pyrole	•	Sodium Hydrochloride	•
Nitrosyl Chloride	•	Phthalic Acid	•	Pyromellitic Acid	•	Sodium Hydroxide	■
Norit Carbon	•	Phytate	•	Quebracho Tannin	•	Sodium Hydro. 20% cold	•
Nuchar	•	Phytate Salts	•	Rag Stock Bleached	•	Sodium Hydro. 20% hot	↑
Oakite 5 Compound	•	Pickling Acid, Sulfuric	•	Rare Earth Salts	•	Sodium Hydro. 50% cold	↑
Oil, Creosote	•	Picric Acid Solutions	•	Rayon Acid Water	•	Sodium Hydro. 50% hot	■
Oil, Emulsified	•	Pine Oil Finish	•	Rayon Spin Bath	•	Sodium Hydro. 70% cold	↑
Oil, Fuel	•	Plating Sol. as follows:	•	Rayon Spin Bath spent	•	Sodium Hydro. 70% hot	■
Oil, Lubricating	•	Brass Cyanide	•	Resorcinol	•	Sodium Hypochlorite	•
Oil, Soluble	•	Bronze-Cyanide	•	River Water	•	Sodium Lignosulfonate	•
Oleic Acid, hot	•	Chromium & Cadmium Cyanide	•	Road Oil	•	Sodium Metasilicate	•
Oleic Acid, cold	•	Cobalt Acid	•	Roccal	•	Sodium Molten	•
Ore Fines-Flotation	•	Copper Acid	•	Rosin-Wood	•	Sodium Nitrate	•
Ore Pulp	•	Copper Alk.	•	Rosin in Alcohol	•	Sodium Nitrite-Nitrate	•
Organic Dyes	•	Gold Cyanide	•	Rosin Size	•	Sodium Perborate	•
Oxalic Acid cold	•	Iron-Acid	•	Rubber Latex	•	Sodium Peroxide	■
Ozone, wet	■	Lead-Fluoro	•	Safral	•	Sodium Persulfate	•
Paint-Linseed Base	•	Nickel Bright	•	Salt Alkaline	•	Sodium Phosphate-Mono	•
Paint-Water Base	•	Platinum	•	Salt Electrolytic	•	Sodium Phosphate-Tri	•
Paint-Remover-Sol. Type	•	Silver-Cyanide	•	Salt Refrig.	•	Sodium Potassium Chloride	•
Paint-Vehicles	•	Tin-Acid	•	Sand-Air Blown Slurry	•	Sodium Salicylate	•
Palmitic Acid	•	Tin Alk. Barrel	•	Sand-Air Phosphatic	•	Sodium Sesquicarbonate	•
Paper Board Mill Waste	•	Zinc Acid	•	Sea Coal	•	Sodium Silicate	•
Paper Coating Slurry	•	Zinc Alk. Cyanide	•	Sea Water	•	Sodium Silcofluoride	•
Paper Pulp	•	Polyacrylonitrile Slurry	•	Selenium Chloride	•	Sodium Stannate	•
Paper Pulp with Amun.	•	Polypentek	•	Sequestrene	•	Sodium Sulfate	•
Paper Pulp with Dye	•	Polysulfide Liquor	•	Sewage	•	Sodium Sulfide	•
Paper Pulp, bleached	•	Polyvinyl Acetate Slurry	•	Shellac	•	Sodium Sulfite	•
Paper Pulp, bleached-washed	•	Polyvinyl Chloride	•	Shower Water	•	Sodium Sulfhydrate	•
Paper Pulp Chlorinated	•	Porcelain Frit	•	Silica Gel	•	Sodium Thiocyanate	•
Paper Groundwood	•	Potash	□	Silica Ground	•	Sodium Thiosulfate	•
Paper Rag	•	Potassium Acetate	•	Silicone Tetrachloride	•	Sodium Tungstate	•

FLUID COMPATIBILITY CHART

for metal threaded fittings sealed with LOCTITE® Sealants

LIQUIDS, SOLUTIONS & SUSPENSIONS

Sodium Xanthate	•	Thorium Nitrate	•	Xylene	•	Oxygen	■
Solox-Denat. Ethanol	•	Thymol	•	Zelan	•	Ozone	■
Soluble Oil	•	Tin Tetrachlorida	•	Zeolite Water	•	Producer Gas 50 PSI	•
Solvent Naphthas	•	Tinning Sol. DuPont	•	Zinc Acetate	•	Propane	•
Sorbic Acid	•	Titania Paper Coating	•	Zinc Bromide	•	Propylene	•
Sour Gasoline	•	Titanium Oxide Slurry	•	Zinc Chloride	•	Steam	■
Soybean Sludge-Acid	•	Titanium Oxy Sulfate	•	Zinc Cyanide-Alk.	•	Sulfur Dioxide	•
Spensol Solution	•	Titanium Sulfate	•	Zinc Fines Slurry	•	Sulfur Dioxide dry	•
Stannic Chloride	•	Titanium Tetrachloride	•	Zinc Flux Paste	•	Sulfur Trioxide Gas	■
Starch	•	Toluol	•	Zinc Galvanizing	•	Sulfuric Acid Vapor	•
Starch Base	•	Toluene	•	Zinc Hydrosulfite	•		
Steam Low Pressure	•	p-Toluene Sulfonic Acid	†	Zinc Oxide in Water	•		
Stearic Acid	•	Transil Oil	•	Zinc Oxide in Oil	•		
Steep Water	•	Trichloroacetic Acid	•	Zinc Sulfate	•		
Sterilization Steam	•	Trichlorethane 1,1,1	•	Zincolate	•		
Stillage Distillers	•	Trichlorethylene	•	Zirconyl Nitrate	•		
Stoddard Solvent	•	Trichlorethylene-Dry	•	Zirconyl Sulfate	•		
Styrene	•	Tricresyl Phosphate	•				
Styrene Butadiene Latex	•	Triethanolamine	•				
Sulfamic Acid	•	Triethylene Glycol	•				
Sulfan-Sulfuric Anhydride	•	Trioxane	•	GASES			
Sulfathiazole	•	Tungstic Acid	•	Acetylene	•		
Sulfite Liquor	•	Turpentine	•	Acid & Alkali Vapours	•		
Sulfite Stock	•	UCon § Lube	•	Air	•		
Sulfonated Oils	•	Udylite Bath-Nickel	•	Amine	•		
Sulfones	•	Undeeylenic Acid	•	Ammonia	•		
Sulfonic Acids	•	Unichrome Sol. Alk.	•	Butane	•		
Sulfonyl Chloride	•	Uranium Salts	•	Butadiene Gas/Liquid	•		
Sulfur Slurry	•	Uranyl Nitrate	•	Butylene Gas/Liquid	•		
Sulfur Solution	•	Uranyl Sulfate	•	By-Product Gas (Dry)	•		
in Carbon Disulfide	•	Urea Ammonia Liquor	•	Carbon Dioxide	•		
Sulphuric Acid 0-7%	†	Vacuum to 100 Micron	•	Carbon Disulfide	•		
Sulphuric Acid 7-40%	†	Vacuum below 100 Micr.	•	Carbon Monoxide	•		
Sulphuric Acid 40-75%	†	Vacuum Oil	•	Chloride Dry	•		
Sulphuric Acid 75-95%	■	Vanadium Pentoxide	•	Chlorine Dry	■		
Sulphuric Acid 95-100%	■	Slurry	•	Chlorine Wet	■		
Sulphurous Acid	†	Varnish	•	Coke-oven Gas-cold	•		
Sulfuryl Chloride	•	Varsol-Naphtha Solv.	•	Coke-oven Gas-hot	†		
Surfactants	•	Versene §	•	Cyanogen Chloride	•		
Synthetic Latex	•	Vinyl Acetate Dry or Chloride Monomer	•	Cyanogen Gas	•		
Taconite - Fines	•	Vinyl Chloride Latex Emul.	•	Ethane	•		
Talc - Slurry	•	Vinyl Resin Slurry	•	Ether-see Diethyl Ether	•		
Tankage - Slurry	•	Viscose	•	Ethylene	•		
Tannic Acid (cold)	†	Vortex-Hydroclone	•	Ethylene Oxide	•		
Tamin	•	Water-Acid - Below pH7	•	Freon § (11-12-21-22)	†		
Tar & Tar Oil	•	Water pH7 to 8	•	Furnace Gas hot	†		
Tartaric Acid	•	Water Alkaline - Over pH8	•	Furnace Gas cold	•		
Television Chemicals	•	Water Mine Water	•	Gas drip oil	•		
Tergitol §	•	Water River	•	Gas flue	•		
Terpineol	•	Water Sandy	•	Gas manufacturing	•		
Tetraethyl Lead	•	Water "White" - low pH	•	Gas natural	•		
Tetrahydrofuran	•	Water "White" - high pH	•	Helium	•		
Tetranitromethane	•	Wax	•	Hydrogen Gas-cold	•		
Textile Dyeing	•	Wax Chlorinated	•	Hydrogen Chloride	•		
Textile Finishing Oil	•	Wax Emulsions	•	Hydrogen Cyanide	•		
Textile Printing Oil	•	Weed Killer Dibromide	•	Hydrogen Sulfide wet & dry	•		
Thiocyanic Acid	•	Weisberg Sulfate Plating	•	Isobutane	•		
Thioglycolic Acid	•	Wood ground pulp	•	Methane	•		
Thionyl Chloride	•	Wort Lines	•	Methyl Chloride	•		
Thiophosphoryl Chloride	•	X-Ray Developing Bath	•	Natural gas dry	•		
Thiourea	•			Nitrogen gas	•		
				Nitrous Oxide	•		
				Oil-Solvent Vapor	•		

NOTE:

- The above information does not constitute a recommendation of sealant use. It is intended only as a guide for consideration by the purchaser with the expectation of favorable confirming test results. It is impossible to test sealant reaction with the multitude of chemicals in existence, therefore, compatibility has been estimated based on a wide variety of customer experience.
- With the stringent action of such chemicals as Freon, strong cold acids and caustics, thorough evaluation is suggested. Sealing of hot corrosive chemicals is not recommended.
- Contact us for use with chemicals not covered by this information.
- This is a list of chemical stability only. It does not constitute approval for use in the processing of food, drugs, cosmetics, pharmaceuticals, and ingestible chemicals. LOCTITE® products are not recommended for use in pure oxygen or chlorine environments or in conjunction with strong oxidizing agents.

§Listing(s) may be Brand Name(s) or Trademarks for chemicals of Corporations other than Henkel.

LOCTITE® MANUFACTURING RELIABILITY WORKSHOP

LOCTITE® Manufacturing Reliability Workshop is a hands-on training program designed to improve operating equipment efficiency and profitability. This process helps your maintenance engineers reduce the costs associated with unscheduled maintenance and sub-component failure. Included in this program is training on identification of common causes of failure of mechanical assemblies and the role of engineering adhesives in equipment reliability and proactive maintenance.

Features:

Pre-plant survey

- Workshop can be tailored to meet your needs through a plant tour and pre-survey

In-plant follow up

- Ensure proper application of learning from the workshop

Training Modules:

- Threadlocking
- Thread Sealing
- Gasketing
- Retaining

Hands-on training

- Job related and product specific
- Review of common failure causes and prevention
- Various applications cover all trades
- Products and hands-on practice components issued
- Training materials supplied
- Conducted on-site

Henkel Adhesives Technologies India Private Limited

Mumbai

Corporate Office

L & T Seawoods, Grand Central,
401, B Wing, 4th Floor, Tower 1,
Seawoods, Navi Mumbai - 400 706,
Maharashtra, India.
Phone : +91 22 7130 1300

Chennai

Arunodayam, No. 14 & 16,
Raman Street, North Boag Road,
T. Nagar, Chennai - 600 017,
Tamil Nadu, India.
Phone : +91 44 7199 7000

Pune

Survey No. 234, 235 and 245,
India Land Global Industrial Park,
Phase 1, Hinjewadi, Pune - 411 057,
Maharashtra, India.
Phone : +91 20 7199 7000

Delhi

74, Industrial Corporation,
Mehrauli Gurgaon road,
Gurgaon - 122 001,
Haryana, India.
Phone : +91 0124 509 7000

Factory

D3/D4, MIDC Industrial Estate,
Jejuri, Purandhar, Pune - 412 303,
Maharashtra, India.
Phone : +91 2115 718 000

www.henkel.in

www.henkel-adhesives.com/in

www.linkedin.com/company/henkel-adhesives