

TECHNICAL DATA SHEET



Go2® Glue

Description: Loctite Go2 Glue is a true all-purpose glue that delivers the power of two technologies to create Durability & Versatility. Mixing the strength of polyurethane & the versatility of polyoxysilane, it is the ideal formula for your repairing, crafting & building jobs. This technology was developed with Loctite Industrial expertise. Go2 Glue dries crystal clear, does not wrinkle paper and sets with no clamping. Go2 Glue is elastic, shock resistant, non-shrinking, fills gaps, water resistant and can be used indoors and outdoors.

Available As:

Item #	Size	Package
1661510 1624417 1698715 1729854	1.75 oz	Carded Bottle
1624412	3.5 oz	Carded Bottle

Features & Benefits:

- Dries Crystal Clear
- Extra Durable & Versatile
- Solvent Free
- Water Resistant
- Temperature Resistance: up to 176°F (80°C)

Recommended For:

Loctite Go2 Glue is ideal for DIY repairs and modeling work in and around the house. It is compatible with many porous and non-porous materials such as aluminum¹, stainless steel, steel, copper¹, brass¹, bronze¹, concrete, tiles, ceramic, glass, mirror¹, wood, cork, chipboard, MDF, varnished surfaces¹, fiberglass reinforced polyester, unfinished leather, linen, paper, cardboard, rigid PVC, polycarbonate, sanded ABS, polystyrene foam, mirrors¹, natural stones, concrete.

¹ See limitations below.

For Best Results:

- Not for use on polyethylene (PE), polypropylene (PP), polytetrafluoroethylene (PTFE), ABS and rigid polystyrene
- Before application, carry out tests to ensure the compatibility of Loctite Go2 Glue with non-ferrous metals such as aluminum, copper, bronze and brass as well as with different coatings such as paints, varnishes and powder coatings. Variations in composition may affect adhesion.
- Loctite Go2 Glue is only compatible with mirrors whose reflection and protective coating complies with DIN 1238 5.1 and DIN EN 1036. See application instructions.
- The cured product is water-resistant, but not suitable for water immersion
- If bonding two non-porous surfaces (i.e. metal to metal or plastic to plastic) then both surface should be pre-wetted with a damp cloth before applying the adhesive. Avoid wetness, pooling water or water drop formation.

Coverage:

0.7 fl oz per ft 2 or 7.7 fl oz / m^2 when applied to one surface only Note: The required amount depends on the substrate porosity and thickness of any gap



Application Temperature:

Maple to Maple: Maple to Aluminum:

TECHNICAL DATA SHEET

Typical Un	cured
Physical P	roperties

Color:	Transparent and Colorless		
Appearance:	Liquid Gel		
Base:	Silane moisture-curing polymer		
Odor:	Minimal		
Specific Gravity:	1.1		
Flash Point:	157°F (69.5°C)		
Viscosity:	8,000 to 20,000 cps		
VOC Content:	8.7% by weight	CARB	
	278.5 g/l	SCAQMD rule 1168	
Shelf Life:	18 months from date of manufacture (unopened)		
Lot Code Explanation:	YYDDD		
Printed on bottom of bottle	YY= Last two digits of year of manufacture DDD= Day of manufacture based on 365 days in a year		
	Example: 5061 = 61st day of 2015 = March 2, 2015		

Typical Application Properties:

Open Time:	8 - 15 minutes*
Repositioning Time:	5 minutes*
Clamp Time:	30 minutes minimum
Cure Time:	Approximately 24 hours*
	*Times are dependent on temperature, humidity, porosity of surface bonded and amount of adhesive used

Apply between 41°F (5°C) to 104°F (40°C)

Typical Cured Performance Properties:

Color:	Clear and Colorless	
Cured Form:	Non-flammable, flexible solid	
Service Temperature:	-40°C (-40°F) to 80°C (176°F) -40°C (-40°F) to 50°C (122°F)	Short Term (Intermittent) Long Term (Continuous)
	Note: Exposures above 50°C (122°F) cause some yellowing	will
Water Resistant:	Yes	
Paint Compatibility:		thane-based varnishes and alkyd resin varnishes. nay be delayed. It is not compatible with one component
Tensile Shear Strength:		7 day cure at 23°C (73°F)
Pine to Pine: Maple to Maple: Maple to Aluminum: Aluminum to Aluminum: Cold rolled steel to itself: Maple to Stainless steel: Stainless steel to itself: Maple to PVC (hard): PVC to PVC (hard): Maple to polycarbonate: Maple to Acrylic (sanded): Maple to ABS: Maple to ABS (sanded): Maple to Fiberglass (sanded):	392 psi (2.70 N/mm²) 493 psi (3.40 N/mm²) 375 psi (2.59 N/mm²) 243 psi (1.68 N/mm²) 189 psi (1.30 N/mm²) 491 psi (3.39 N/mm²) 496 psi (3.42 N/mm²) 218 psi (1.50 N/mm²) 109 psi (0.75 N/mm²) 473 psi (3.26 N/mm²) 234 psi (1.61 N/mm²) 119 psi (0.82 N/mm²) 371 psi (2.56 N/mm²) 450 psi (3.10 N/mm²)	1 square inch bond area
Tensile Shear Strength:		7 day cure, 3 hr water immersion

471 psi (3.25 N/mm²) 370 psi (2.55 N/mm²)



TECHNICAL DATA SHEET

Compression Shear Strength: 7 day cure

Maple to Maple: 466 psi (3.2 N/mm²)

Peel Strength: 7 day cure

Canvas to Canvas: 4 lb/inch (0.7 N/mm)
Canvas to Pine: 11 lb/inch (1.9 N/mm)
Corduroy to Maple: 6 lb/inch (1.0 N/mm)
Felt to Pine: 9 lb/inch (1.6 N/mm)
Unfinished Leather to Pine: 8 lb/inch (1.4 N/mm)

Directions:

Safety Precautions:

Wear gloves and wash hands after use.

Preparation:

Protect work area. Surfaces to be glued must be sound, clean, dry (see Application below) and free of grease, dust, old adhesive residue, paint and other contaminants such as plasticizers and mold release agents. Remove contaminants with alcohol or acetone (tests surfaces for compatibility before). For improved adhesion, lightly sand very smooth or glossy surfaces and clean thoroughly. Pre-fit all materials before applying adhesive. When bonding two non porous surfaces, dampen surfaces lightly before applying adhesive. Mask off the adjacent areas with tape before gluing if necessary. To open, rotate cap counterclockwise.

Application:

Apply a thin layer of adhesive to one surface. Bond parts immediately after applying the adhesive and hold or clamp parts together (before skin formation) for at least 30 minutes. For best results allow 24 hours cure before subjecting to stress. Unlike other adhesives, high pressure during curing is not necessary. Very porous materials will require a thicker layer of adhesive and application to both surfaces may be required.

Loctite® Go2® Glue cures by absorbing moisture into the bond line from the ambient air (air humidity or water vapor) or from the substrate. If both surfaces to be joined are non-porous (i.e. metal to metal or plastic to plastic) then they can only be glued by pre-wetting both surfaces with a damp cloth before applying the adhesive. Avoid wetness, pooling water or water drop formation. For large surface areas make sure the moisture film does not dry off before applying the adhesive. Absorbent surfaces are normally water-permeable and do not require pre-wetting; however, the curing process can be considerably accelerated for both absorbent and non-absorbent substrates if the surfaces are pre-wetted by wiping the areas to be glued with a damp cloth before applying the adhesive. The adhesive can be applied to damp surfaces. The adhesive will reach its maximum strength after it has fully cured and the substrates have fully dried.

After setting, the adhesive can be painted, especially with water based acrylic paint.

Mirror bonding: Be very careful not to scratch or damage the back coating of the mirror. Protect surrounding areas and floors from drips, squeeze outs etc. Apply the adhesive to the back of the mirror or the substrate in vertical beads approximately 1/8 inch (3 mm) wide and approximately 1-2 inches (2.5-5 cm) apart. Do not place the adhesive too close to the edge to prevent squeeze out (leave approximately 1-2 inches (2.5-5 cm) from the edges). Within 5-8 minutes place firmly up against the wall and tape in place until cured. Support the bottom of the mirror to prevent slippage until the adhesive cures. For mirrors larger than 1 square foot (0.09 m^2) , this product must be used with a permanent support system. Place mirror into support channels or hangers and press in place within 5-8 minutes. Tape or brace the top of the mirror until the adhesive has set at least 48 hours. For non-porous surfaces longer curing time will be required. Do not try to reposition the mirror once in place. If sealing the edges wait a minimum of 7 days. Curing time will depend on temperature, humidity, type of substrate and amount of air that can reach the adhesive.

Clean-up:

Clean tools and adhesive residue immediately after use with alcohol, acetone or cleaner's naphtha. Cured sealant may be carefully cut away with a sharp-edged tool. Cured adhesive cannot be removed from clothing and is not soluble in any solvent.

Storage & Disposal:

Store above freezing in a cool and dry place. Avoid direct sunlight. Close the tube tightly immediately after each use. Exposure to high humidity during storage will reduce shelf life. Exposure to high temperatures during storage (> 122°F, 50°C) will cause the product to yellow in the bottle.

To dispose of unwanted product, squeeze out remaining material, allow to dry and discard with domestic waste. Dispose of non-hardened product residues according to the applicable local regulations. Large product amounts must be disposed of separately. The empty packaging can be recycled.

Label Precautions:

WARNING! COMBUSTIBLE. MAY CAUSE SKIN AND EYE IRRITATION. Contains trimethoxysilanes. Keep away from heat, sparks and flame. May be harmful if inhaled or swallowed. Methanol is released during application and cure, which may affect the nervous system causing dizziness, headache or nausea. Use in a well ventilated area. Do not breathe vapors. Avoid eye and skin contact. Prolonged or repeated skin contact may cause dermatitis. Wash hands after using. Wear gloves when applying product. FIRST AID: For eye contact flush with water for 15 minutes. Call a physician if irritation develops and persists. For skin contact, wash with soap and water. If affected by inhalation, remove to fresh air and get medical attention. If ingested, do not



TECHNICAL DATA SHEET

induce vomiting. Call a physician or Poison Control Center immediately. DO NOT TAKE INTERNALLY. KEEP OUT OF REACH OF CHILDREN.

WARNING: This product contains chemicals known to the State of California to cause cancer.

Refer to Safety Data Sheet (SDS) for further information.

Disclaimer:

The information and recommendations contained herein are based on our research and are believed to be accurate, but no warranty, express or implied, is made or should be inferred. Purchasers should test the products to determine acceptable quality and suitability for their own intended use. Nothing contained herein shall be construed to imply the nonexistence of any relevant patents or to constitute a permission, inducement or recommendation to practice any invention covered by any patent, without authority from the owner of the patent.



Trusted Performance. Proven Results.

For over 50 years, Loctite Brand adhesives and sealants have taken on the toughest jobs. Used in race cars, airplanes, and even in the space-shuttle, Loctite provides solutions for the most demanding industrial, professional and consumer applications. Loctite gives you not the specialization, power and performance to not only get your job done, but to get it done right.

1-800-624-7767 – Mon-Fri - 9:00a – 4:00p ET www.loctiteproducts.com



Loctite Brand is part of the Henkel family of brands. Founded in 1876, Henkel is a global leader in the consumer and industrial businesses. Henkel operates worldwide with leading brands and technologies in three business areas: Laundry & Home Care, Beauty Care and Adhesive Technologies.

Henkel Corporation - Professional & Consumer Adhesives Headquarters - Rocky Hill, CT 06067 www.henkelna.com

Revision Date: 09/12/2016 Supercedes: 03/19/2014 Ref. #: 1690076