



**Henkel Corporation**

26235 First Street  
Westlake, OH 44145  
(440) 250-7700  
Fax (440) 250-7867  
[www.henkelna.com](http://www.henkelna.com)

To Whom It May Concern:

In response to your request for a Safety Data Sheet (SDS) for OSI Butyl Flashing Tape, we offer the following information:

The material in question is an "article" as defined by the United States Department of Labor, Occupational Safety and Health Administration (OSHA) and is a "manufactured article" as defined by the Canadian Hazardous Products Act (R.S.C., 1985, c. H-3) and as such is exempt from the requirement for creation of a SDS.

US Federal OSHA defines an "article" as follows at 29 CFR 1910.1200 (c):  
*Article* means a manufactured item other than a fluid or particle: (i) which is formed to a specific shape or design during manufacture; (ii) which has end use function(s) dependent in whole or in part upon its shape or design during end use; and (iii) which under normal conditions of use does not release more than very small quantities, e.g., minute or trace amounts of a hazardous chemical (as determined under paragraph (d) of this section), and does not pose a physical hazard or health risk to employees.

OSI Butyl Flashing Tape, does not have an intended release in the application or use of the product. Any product which meets the definition of an "article" or a "manufactured article" is exempt from the requirement to provide an SDS.

Find our SDSs on the Internet at [www.henkelna.com/industrial/msds-search-5120.htm](http://www.henkelna.com/industrial/msds-search-5120.htm)

If you have any questions, please contact the undersigned at (440) 250-7700

Sincerely,

A handwritten signature in black ink that reads "Mary Ellen Boddy".

Manager, Regulatory Affairs